



## D&D Facility Characterization Interview Checklist

ID No.: <u>772A</u>

Date: 10/09/00

Page 1 of 2

Check List for	- Title: D&D	Facility (	Characterization – Interviews	;
----------------	--------------	------------	-------------------------------	---

CRITERIA: A D&D Characterization Protocol, RFETS MAN-077-DDCP, Rev. 0

 $\Lambda$  Facility Disposition Program Manual, RFETS MAN-076-FDPM

 $\Lambda$  RFETS Radiological Safety Practices, January 12, 1998

Facility Name & Type (1, 2, or 3) Buildings 772A, Type 1Facility, HF Caustic Scrubber Equipment Pit
Personnel Interviewed (Name & Title/Function) Don L. Cox, Mechanical Engineer V, D&D Closure
Y/N
Does a current WSRIC exist for the facility?
If so, are there exceptions to the WSRIC as written?
COMMENTS (incl. WSRIC contacts)
WSRIC Contact is James M. Schoen who is in charge of the WSRIC Reports, T130J, X3579, C-83.  Are rad surveys available that indicate current status of the facility?
Are historical rad surveys available that indicate historical status, or evolution, of the facility?
Are historical rad surveys available that indicate historical status, or evolution, of the facility?
COMMENTS N* According to Sarah J. Roberts, X3008, ACRDA, T771Q, any historical data, which is
probably ay the Federal Center, would not be adequate for unrestricted release (i.e. Pre-Demolition Survey
or Property Release Evaluation). New monitor surveys would have to be taken.  Is an HRR available for the facility?
Is an HRR available for the facility?
Characterize the facility relative to chemical &/or radiological contamination?
If so, what are the issues (note in Comments, below)?
COMMENTS The building does not sit on IHSS/PACC area land/soil.
Marya any tymos of about all about a feet as feet as boots. As a markay and according
Have any types of chemical characterization, incl. asbestos, been performed recently? N
If an archaet transport of the control of the contr
If so, what types of characterization were performed (note in Comments, below)?
COMMENTS The building was never completed and no equipment was ever installed.
Interviewed by: D. A. Burton / LOBent / 10/09/00
Interviewed by: D. A. Burton / 10/09/00
Print Name Signature Interview Date



## D&D Facility Characterization Interview Checklist

ID No.: 772A

Date: \_\_10/09/00\_

Page 2 of 2

What timeframe	did the interviewee work	in the facility? <u>N/A.</u>		
		ce you worked in the building t beams were ever installed. N	? If so, in what way? lo equipment was put into place.	
	• •	ling during the interviewee's ti		
Where was the e	equipment located? (specif	ic rooms/areas) N/A		-
Were any radioa	ctive materials or metals h	andled in the building? If so,	what types? <u>No</u>	
Which equipmen	t handled radioactive mate	erial? <u>None</u>		
Were any chemic	cals handled in the building	g? If so, what types? No.		
Did any spills or facility? No	uncontrolled releases of ra	adioactive materials or chemica	als occur while you were working in t	the
Were these spills	s/releases cleaned-up? <u>N/A</u>	<u>.</u>		
Where did these	spills/releases occur? N/A			
Interviewed by:	D. A. Burton Print Name	/ MMeura Signature	/ <u>10/09/00</u> Interview Date	
	i intervanio	Signaturo	might for build	



